F56-BDU **ERROR CODE LIST** CONFIDENTIAL E02 May 2007 E01 May 2006 FUJITSU FRONTECH LIMITED Tokyo, Japan F56-BDU ERROR CODE LIST DRAW, NO. K3KD03234-0001 DATE DESIG. CHECK APPR. DESCRIPTION **FUJITSU FRONTECH LTD. /** 27 CHECK APPR. FMV WORD KDXC-4979-1 02.07

The contents of this manual shall not be disclosed in any way or reproduced in any media vexpress written permission of Fujitsu Frontech Limited. The contents of this manual may be revised without prior notice.	without the	
The contents of this manual may be revised without prior notice.		
TITLE F56-BDU ERROF	R CODE LIS	ST
DRAW. NO. K3KD03234-000		CUST
EDIT DATE DESIG. CHECK APPR. DESCRIPTION DESIG. CHECK APPR. APPR. FUJITSU FRONTECH FMV WORD		2/ ₂₇ 9-1 02.

Update History

ED.	DATE	DESCRIPTION
E01	2006.05.20	First edition created from error code of F56-BDU.(Rohs)
E02	2007.05.20	Error code 1100,1200-1205,1500,1600-1605,2100,2200-2205,2500,2600-2605, 3100,3200-3205,3500,3600-3605,4100,4200-4205,4500,4600-4605, F80F, F88F, F8AF is additions.
		COMPLETION

							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE 3.	DESIG.	CHECK	APPR.	DESCRI APPR.	PTION	FUJITSU FRONTECH LTD.	3/27

CONTENTS

1.	Outline	5
	1.1 Error Code	5
	1.2 Error Code List	
	1.3 7seg display	.10
2.	Error code details	.11
	2.1 System down	
	2.2 1st / 5th Cassette section	.12
	2.3 2nd / 6th Cassette section	.13
	2.4 3rd / 7th Cassette section	.14
	2.5 4th / 8th Cassette section	.15
	2.6 Bill pool section	.16
	2.7 Transfer section	.17
	2.8 Bill check section	
	2.9 Ejection / Shutter section	.22
	2.10 Rejection / Capture box section	
	2.11 Error related to the download	.24
	2.12 D level error	
	2.13 RD Controller	26


\vdash					_			
							F56-BDU ERROR CODE LIS	ST
F							DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	S H E	4/
DESIG	s.		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

1. Outline

This document is described for error cords that occur on F56-BDU.

1.1 Error Code

Error Code which are set in the negative response are classified follows:



- (1) Upper 4 bits of 1st byte show a position in which an error occurred. Lower 4 bits show detailed information of the error.
- (2) 2nd byte shows additional information for the error code.

\vdash							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	5/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

1.2 Error Code List

	System down	1st / 5th Cassette section		
00		10	No 1st Cassette	
01		11	1st cassette empty	
02		12	1st cassette: Error related to bill diagnosis	
03	Internal error	13		
04	Internal error	14	No 5th Cassette	
05		15	5th cassette empty	
06		16	5th cassette: Error related to bill diagnosis	
07		17		
80		18	1st Cassette pick error	
09		19		
0A		1A		
0B		1B		
0C		1C	5th Cassette pick error	
0D		1D		
0E		1E		
0F		1F		

	2nd / 6th Cassette section		3rd / 7th Cassette section
20	No 2nd Cassette	30	No 3rd Cassette
21	2nd cassette empty	31	3rd cassette empty
22	2nd cassette: Error related to bill diagnosis	32	3rd cassette: Error related to bill diagnosis
23		33	
24	No 6th Cassette	34	No 7th Cassette
25	6th cassette empty	35	(7th cassette empty)
26	6th cassette: Error related to bill diagnosis	36	7th cassette: Error related to bill diagnosis
27		37	
28	2nd Cassette pick error	38	3rd Cassette pick error
29		39	
2A		3A	
2B		3B	
2C	6th Cassette pick error	3C	(7th Cassette pick error)
2D		3D	
2E		3E	
2F		3F	

\vdash							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	6/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

	4th / 8th Cassette section		Bill pool section
40	No 4th Cassette	50	Home position error
41	4th cassette empty	51	Upper position error
42	4th cassette: Error related to bill diagnosis	52	No bill in pool section
43		53	
44	No 8th Cassette	54	
45	(8th cassette empty)	55	
46	8th cassette: Error related to bill diagnosis	56	
47		57	
48	4th Cassette pick error	58	
49		59	
4A		5A	
4B		5B	
4C	(8th Cassette pick error)	5C	
4D		5D	
4E		5E	
4F		5F	

	Reserve	Transfer section		
60		70	Medium remain	
61		71	•	
62		72		
63		73		
64		74		
65		75		
66	M.	76	Medium pulling out	
67	0/2	77		
68		78	JAM (FDLSn~DFSS)	
69		79		
6A		7A	JAM (DFSS~BPS)	
6B		7B	JAM (DFSS∼REJS)	
6C		7C	JAM (pool section ~ EJSF/EJSR)	
6D		7D	JAM (EJSF/EJSR ~ pool section)	
6E		7E		
6F		7F		

\vdash							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							K3KD03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	8 1 1	7/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

	Bill check section		Reserve
80		90	
81		91	
82	Bill length error (long)	92	
83	Bill length error (short)	93	
84	Thickness error	94	
85	Pick from another safe	95	
86	Abnormal spacing	96	
87		97	
88	Count mismatch	98	
89	Potentiometer error	99	
A8		9A	
8B		9B	
8C		9C	
8D		9D	
8E		9E	
8F		9F	

	Ejection / Shutter section		Rejection / Capture box section
Α0		В0	
A1	(Front) Shutter open error	B1	
A2	(Front) Shutter close error	-82	
Α3		₽3	
A4	(Front) No bills in the ejection opening	B4	
A5		B5	Reject box overflow
A6	W.	B6	
Α7	(Front) Open shutter	В7	
A8	$\mathcal{G}_{\mathcal{G}}$	B8	(Front) Capture box (option) is no setup
A9	(Rear) Shutter open error	В9	(Front) Capture box is no set
AA	(Rear) Shutter close error	ВА	(Front) Capture box overflow
AB		BB	
AC	(Rear) No bills in the ejection opening	ВС	(Rear) Capture box (option) is no setup
AD		BD	(Rear) Capture box is no set
ΑE		BE	(Rear) Capture box overflow
AF	(Rear) Open shutter	BF	

							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	8 1 1	8/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

	Error related to the download		Reserve
C0	Sequence error	D0	
C1	Download error	D1	
C2	Command received except RT, LD and LE	D2	
C3	Download error	D3	
C4		D4	
C5		D5	
C6		D6	
C7		D7	
C8		D8	
C9		D9	
CA		DA	
CB		DB	
CC		DC	
CD		DD	
CE		DE	
CF		DF	

	D level error	BD controller			
E0	RAS command undefined	F0			
E1	Parameter not registered	F1	Over current error		
E2		ΨŽ	Option setup is unusual.		
E3		F 3	(Front) Option setup is unusual.		
E4	Bill information not provided	F4	(Rear) Option setup is unusual.		
E5	Specification error	F5			
E6	Parameter ISO code error	F6	Log data check sum error		
E7	0/4	F7			
E8	Bill length/ thickness information error	F8	Sensor error		
E9		F9			
EA	Parameter error	FA			
EB		FB			
EC	FS error	FC	Illegal operation (F56S)		
ED		FD	Power off during count (F56S)		
EE	Command format error	FE			
EF	Command execution is impossible.	FF			

						F56-BDU ERROR CODE LIS	ST
						— K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	SHE	9/
DESIG	S		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

1.3 7seg display

State of display

No.	Display	State
1	0	Normal state
2	1	The program down loaded incompletely.
3	r	RAS operation in progress

System down of display (Power off-on is necessary)

No.	Display	Description			
1	3.	ROM check sum error			
2	4.	RAM check error			
3	5.	Watch dog error			
4	6.	Transmit error (BOOT)			
5	7.	FRAM check error			
6	d.	System down			
6 d. System down					

2. Error code details

2.1 System down

Semi- major	Additional Information	Detailed information
03	01	Internal error 1
03	02	Internal error 2
04	xx	Internal error 3 xx: Task ID

						F56-BDU ERROR CODE LIS	ST
\vdash						DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S	11/
DESIG	S.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

2.2 1st / 5th Cassette section

Semi- major	Additional Information	Detailed information
10	00	No 1st Cassette.
11	00	1st cassette empty(pick errors while bills low)
	00	1st cassette diagnosis data none
	01	1st cassette denomination differs
	02	1st cassette: The reference value of length cannot be fixed
12	03	1st cassette: The reference value of the thickness cannot be fixed
	04	1st cassette: The length diagnosis result is outside a regulated range
	05	1st cassette: The thickness diagnosis result is outside a regulated range (0.09 mm $-$ 0.15 mm)
14	00	No 5th Cassette.
15	00	5th cassette empty (pick errors while bills low)
	00	5th cassette diagnosis data none
	01	5th cassette denomination differs
	02	5th cassette: The reference value of length cannot be fixed
16	03	5th cassette: The reference value of the thickness cannot be fixed
	04	5th cassette: The length diagnosis result is outside a regulated range
	05	5th cassette: The thickness biasposis result is outside a regulated range $(0.09~\text{mm}-0.15~\text{mm})$
		CH.
18	00	1st Cassette pickerro
1C	00	5th Cassette pick error.

						F56-BDU ERROR CODE LIS	ST
						DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	SHE	12/
DESIG	S		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

2.3 2nd / 6th Cassette section

Semi- major	Additional Information	Detailed information			
20	00	No 2nd Cassette.			
21	00	2nd cassette empty(pick errors while bills low)			
	00	2nd cassette diagnosis data none			
	01	2nd cassette denomination differs			
	02	nd cassette: The reference value of length cannot be fixed			
22	03	2nd cassette: The reference value of the thickness cannot be fixed			
	04	2nd cassette: The length diagnosis result is outside a regulated range			
	05	2nd cassette: The thickness diagnosis result is outside a regulated range (0.09 mm $-$ 0.15 mm)			
24	00	No 6th Cassette.			
25	00	6th cassette empty(pick errors while bills low)			
	00	6th cassette diagnosis data none			
	01	6th cassette denomination differs			
	02	6th cassette: The reference value of length cannot be fixed			
26	03	6th cassette: The reference value of the thickness cannot be fixed			
	04	6th cassette: The length diagnosis result is outside a regulated range			
	05	6th cassette: The thickness 0 is result is outside a regulated range $(0.09 \text{ mm} - 0.15 \text{ mm})$			
		N.			
28	00	2nd Cassette pick error.			
2C	00	6th Cassette pick error.			

\vdash				_			I	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							K3KD00234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	13/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.4 3rd / 7th Cassette section

Semi- major	Additional Information	Detailed information
30	00	No 3rd Cassette.
31	00	3rd cassette empty(pick errors while bills low)
	00	3rd cassette diagnosis data none
	01	3rd cassette denomination differs
	02	3rd cassette: The reference value of length cannot be fixed
32	03	3rd cassette: The reference value of the thickness cannot be fixed
	04	3rd cassette: The length diagnosis result is outside a regulated range
	05	3rd cassette: The thickness diagnosis result is outside a regulated range (0.09 mm $-$ 0.15 mm)
34	00	No 7th Cassette.
35	00	(7th cassette empty(pick errors while bills low))
	00	7th cassette diagnosis data none
	01	(7th cassette denomination differs)
	02	(7th cassette: The reference value of length cannot be fixed)
36	03	(7th cassette: The reference value of the thickness cannot be fixed)
	04	(7th cassette: The length diagnosis result is outside a regulated range)
	05	(7th cassette: The thickness diagnosis result is outside a regulated range (0.09 mm $-$ 0.15 mm))
		N.
38	00	3rd Cassette pick arrow.
3C	00	(7th Cassette pick error)

							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	14/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.5 4th / 8th Cassette section

Semi- major	Additional Information	Detailed information
40	00	No 4th Cassette.
41	00	4th cassette empty(pick errors while bills low)
	00	4th cassette diagnosis data none
	01	4th cassette denomination differs
	02	4th cassette: The reference value of length cannot be fixed
42	03	4th cassette: The reference value of the thickness cannot be fixed
	04	4th cassette: The length diagnosis result is outside a regulated range
	05	4th cassette: The thickness diagnosis result is outside a regulated range (0.09 mm $-$ 0.15 mm)
44	00	No 8th Cassette.
45	00	(8th cassette empty(pick errors while bills low))
	00	8th cassette diagnosis data none
	01	(8th cassette denomination differs)
	02	(8th cassette: The reference value of length cannot be fixed)
46	03	(8th cassette: The reference value of the thickness cannot be fixed)
	04	(8th cassette: The length diagnosis result is outside a regulated range)
	05	(8th cassette: The thickness diagnosis result is outside a regulated range $(0.09~\mathrm{mm}-0.15~\mathrm{mm}))$
48	00	4th Cassette pick arrow
4C	00	(8th Cassette pick error)

\vdash							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	15/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.6 Bill pool section

Semi- major	Additional Information		Detailed information								
50	00	Home pos	Home position error of the pool section								
30	01	Pool sect	ion lower	ing retry	over.						
51	00	Upper po	Upper position error of the pool section								
31	02	Pool sect	ion lifting	retry ove	er.						
52	xx	No mediu XX: Data b7 BRS1			ion. eous (sen b4 EJSR	sor port of b3 EJSF	content) b2 REJS	b1 BPS	b0 DFSS		

						F56-BDU ERROR CODE LIS	ST
						DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S H E	16/
DESIG	à.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

2.7 Transfer section

Semi- major	Additional Information	Detailed information			
	01	Medium remaining at FDLS1.			
	02	Medium remaining at FDLS2.			
	03	Medium remaining at FDLS3.			
	04	Medium remaining at FDLS4.			
	05	Medium remaining at FDLS5.			
	06	Medium remaining at FDLS6.			
	07	(Medium remaining at FDLS7.)			
	08	(Medium remaining at FDLS8.)			
70	09	Medium remaining at DFSS.			
	0A	(Medium remaining at REJS.)			
	0B	Medium remaining at BPS.			
	0C	Medium remaining at BRS1.			
	0D	Medium remaining at BRS2.			
	0E	Medium remaining at BRS3.			
	0F	Medium remaining at EJSF.			
	10	Medium remaining at EJSR.			
76	00	The bill on EJSF was pulled but besides the unit during bill retrieval.			
70	01	The bill on EJSR was pulled out besides the unit during bill retrieval.			

\vdash							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	17/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

Semi-	Additional				
major	Information	Detailed information			
	01	JAM occurred on FDLS1.			
	02	JAM occurred on FDLS2.			
	Information 01	JAM occurred on FDLS3.			
	04	JAM occurred on FDLS4.			
	05	JAM occurred on FDLS5.			
	06	JAM occurred on FDLS6.			
	07	(JAM occurred on FDLS7.)			
	08	(JAM occurred on FDLS8.)			
	11	JAM occurred between FDLS1 and DFSS.			
	12	JAM occurred between FDLS2 and DFSS.			
	13	JAM occurred between FDLS3 and DFSS.			
	14	JAM occurred between FDLS4 and DFSS.			
	15	JAM occurred between FDLS5 and DFSS.			
	16	JAM occurred between FDLS6 and DFSS.			
	17	(JAM occurred between FDLS7 and DFSS.)			
	18	(JAM occurred between FDLS8 and DFSS.)			
78					
70	21	FDLS1 medium remaining after completion of count.			
	22	FDLS2 medium remaining after completion of count.			
	23	FDLS3 medium remaining after completion of count.			
	24	FDLS4 medium remarking after completion of count.			
	25	FDLS5 medium remaining after completion of count.			
	26	FDLS6 medium remaining after completion of count.			
	27	(FDLS7 medium remaining after completion of count.)			
	28	(FDLS8 medium remaining after completion of count.)			
	31	FDLS1 medium remaining after completion of cleaning JAM.			
	32	FDLS2 medium remaining after completion of cleaning JAM.			
	33	FDLS3 medium remaining after completion of cleaning JAM.			
	34	FDLS4 medium remaining after completion of cleaning JAM.			
	35	FDLS5 medium remaining after completion of cleaning JAM.			
	36	FDLS6 medium remaining after completion of cleaning JAM.			
	37	(FDLS7 medium remaining after completion of cleaning JAM.)			
	38	(FDLS8 medium remaining after completion of cleaning JAM.)			

						F56-BDU ERROR CODE LIS	ST
						——————————————————————————————————————	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S H E	18/
DESIG	3.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

Semi-	Additional	Date that it for more in					
major	Information	Detailed information					
	41	FDLS1 was turned on when there was no bill.					
	42	FDLS2 was turned on when there was no bill.					
	43	FDLS3 was turned on when there was no bill.					
	44	FDLS4 was turned on when there was no bill.					
78	45	FDLS5 was turned on when there was no bill.					
	46	FDLS6 was turned on when there was no bill.					
	47	(FDLS7 was turned on when there was no bill.)					
	48	(FDLS8 was turned on when there was no bill.)					
	01	JAM occurred on DFSS.					
	02	JAM occurred between DFSS and BPS.					
	03	JAM occurred on BPS.					
	29	DFSS medium remaining after completion of count.					
7A	2A	BPS medium remaining after completion of count.					
//\							
	39	DFSS medium remaining after completion of cleaning JAM.					
	3A	BPS medium remaining after completion of cleaning JAM.					
	49	DFSS was turned on when there was no bill.					
	01	JAM occurred between NFSS and REJS.					
7B		, and the second					
'-	4B	REJS was turned on when there was no bill					
		$\sim O^{\prime}$					

						F56-BDU ERROR CODE LIS		
\vdash						DRAW. NO. K3KD03234-0001	CUST	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	SHE	19/	
DESIG	i.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27	

Semi- major	Additional Information	Detailed information					
	01	Jam occurred between pool section and EJSF.					
	02	Jam occurred between pool section and EJSR.					
	03	The bill was detected at the same time with EJSF and BRS2 while transporting the bill.					
	04	The bill was detected at the same time with EJSF and BRS1 while transporting the bill.					
	05	The bill was detected at the same time with EJSR and BRS3 while transporting the bill.					
	06	The bill was detected at the same time with EJSR and BRS1 while transporting the bill.					
7C	07	The bill was detected at the same time with EJSR and BRS2 while transporting the bill.					
	2C	EJSF medium remaining after completion of count.					
	2D	EJSR medium remaining after completion of count.					
	3C	EJSF medium remaining after completion of cleaning JAM.					
	3D	EJSR medium remaining after completion of cleaning JAM.					
	80	EJSF was turned on during transfer motor rotation before the mechanical reset operation and feed operation of the bill count command.					
	81	EJSR was turned and tring transfer motor rotation before the mechanical reset operation and teed operation of the bill count command.					
	_	W.					
	01	Jam occurred between EJSF and pool section.					
	02	Jam occurred between EJSR and pool section.					
7D	11	Jam occurred between pool section and EJSR. (Front Retrieval)					
	12	Jam occurred between pool section and EJSF. (Rear Retrieval)					

						F56-BDU ERROR CODE LIS		
						DRAW. NO. K3KD03234-0001	CUST	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S H	20/	
DESIG	S.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27	

2.8 Bill check section

Semi- major	Additional Information	Detailed information					
82	00	Long bill					
83	00	Short bill					
84	00	Thickness abnormal					
	01	Pick from another safe. (1st cassette)					
	02	Pick from another safe. (2nd cassette)					
85	03	Pick from another safe. (3rd cassette)					
00	04	Pick from another safe. (4th cassette)					
	05	Pick from another safe. (5th cassette)					
	06	Pick from another safe. (6th cassette)					
86	00	Spacing between picking bills in less than the specified value.					
	00	Count inconsistency (Number of requested notes = number of notes identified as normal = number of notes that passed through BPS does not hold.)					
88	01	Count inconsistency (BPS was turned ON when there was no bill.)					
	03	Count mismatch (Medium passed through BPS while clearing a jam.)					
89	xx	Potentiometer error xx: Data when judged erroneous (DFCS measured data)					

						F56-BDU ERROR CODE LIS		
							DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	S H E	21/
DESIG	i.		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.9 Ejection / Shutter section

Semi-	Additional	Detailed information									
major	Information 00	Front) Shutter open error (SCSF does not change)									
A1	01										
AI		(Front) Shutter open error (SOSF does not change)									
	02	(Front) Shutter open error (Simultaneous sensor detection)									
4.0	00	(Front) Shutter close error (SOSF does not change)									
A2	01	(Front) Shutter close error (SCSF does not change)									
	02	(Front) Shutter close error (Simultaneous sensor detection)									
A4	XX	(Front) No medium in the ejection section. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 BRS1 BRS2 BRS3 EJSR EJSF REJS BPS DFSS									
A7	XX	(Front) Open shutter. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 TUS THS RJBR RJBF SOSR SCSR SOSF SCSF									
	00	(Rear) Shutter open error (SCSR does not change)									
A9	01	(Rear) Shutter open error (SOSR does not change)									
	02	(Rear) Shutter open error (Simultaneous sensor detection)									
	00	(Rear) Shutter close errock(SCR does not change)									
AA	01	(Rear) Shutter close enco (SCSR does not change)									
	02	(Rear) Shutter close ervor (Simultaneous sensor detection)									
AC	XX	(Rear) No medium in the ejection section. XX: Data when judged erroneous (sensor port content) b7									
AF	xx	(Rear) Open shutter. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 TUS THS RJBR RJBF SOSR SCSR SOSF SCSF									

							F56-BDU ERROR CODE L	IST
							DRAW. NO. K3KD03234-0001	CUST
ı								
EDIT	DATE	DESIG.	CHECK	APPR.	DESCF	IPTION	SHE	22/
DESIG	3.		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.10 Rejection / Capture box section

Semi- major	Additional Information	Detailed information
B5	xx	Reject box was full. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 BRS1 BRS2 BRS3 EJSR EJSF REJS BPS DFSS
В8	xx	(Front) Capture box (option) is no setup XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 RRBOX RSHT FRBOX FSHT
В9	xx	(Front) Capture box is no set XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 TUS THS RJBR RJBF SOSR SCSR SOSF SCSF
ВА	xx	(Front) Capture box was full. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 BRS1 BRS2 BRS3 EJSR EJSF REJS BPS DFSS
ВС	XX	(Rear) Capture box (option) is no setup XX: Data when judged erroneous (sensor port content) b7
BD	xx	(Rear) Capture box is no set XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 TUS THS RJBR RJBF SOSR SCSR SOSF SCSF
BE	XX	(Rear) Capture box was full. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 BRS1 BRS2 BRS3 EJSR EJSF REJS BPS DFSS

							F56-BDU ERROR CODE L	IST
							DRAW. NO. K3KD03234-0001	CUST
ı								
EDIT	DATE	DESIG.	CHECK	APPR.	DESCR	IPTION	SHE	23/
DESIG	3.		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

2.11 Error related to the download

Semi- major	Additional Information	Detailed information					
	00	Received D level command during RAS mode.					
C0	01	Received "LE" during executing RAM program.					
	02	Received "LE" before receiving "LD" command.					
	00	After receiving the 'RT', a loss in the download program.					
	01	Flash ROM write error.					
	02	Sum check error of program load.					
C1	03	After receiving the 'RT', version error.					
	04	Flash ROM erase error.					
	05	File name error of control area format.					
	06	Data size error of control area format.					
C2	01	BD received the command excluding "RT", "LD", and "LE".					
	01	Download header error. (D-Code is not '00')					
C3	02	Download header error. (E-Code is not '1' or 'H')					
US	03	Block number error. (D-code is 'LD')					
	04	Data length error.					

						F56-BDU ERROR CODE LIS		
\vdash						DRAW. NO. K3KD03234-0001	CUST	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S H E	24/	
DESIG	S		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27	

2.12 D level error

Semi-	Additional	Detailed information								
major	Information									
E0	00	RAS command undefined								
E1	00	An attempt was mode to execute a count system request for device's initialization, although no bill information was registered.								
	01	Bill information not provided. (1st cassette)								
	02	Bill information not provided. (2nd cassette)								
E4	03	Bill information not provided. (3rd cassette)								
L4	04	Bill information not provided. (4th cassette)								
	05	Bill information not provided. (5th cassette)								
	06	Bill information not provided. (6th cassette)								
	01	Count sequence specification error								
E5	xx	Specification error of total number of notes xx: Data when judged erroneous (error data)								
E6	xx	Parameter ISO code error xx: Data when judged erroneous (error data)								
E8	xx	Note length/thickness information error xx: Data when judged erroneous (error data)								
EA	xx	Parameter error xx: Data when judged errone (error data)								
EC	xx	FS error xx: Data when judged en oneous (error data)								
EE	xx	Command formatierror xx: Data when judged erroneous (error data)								
EF	xx	Command execution is impossible. (Pool section is no setup) XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 F56SF TRM2 TRM1 TRM0 F56P -								

						F56-BDU ERROR CODE LIS	ST
						DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	SHE	25/
DESIG	S.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27

2.13 BD Controller

Semi- major	Additional Information	Detailed information								
F1	00	Over current error								
F2	xx	Option setup is unusual. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 RRBOX RSHT FRBOX FSHT								
F3	(Front) Option setup is unusual. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 RRBOX RSHT FRBOX FSHT									
F4	(Rear) Option setup is unusual. XX: Data when judged erroneous (sensor port content) b7 b6 b5 b4 b3 b2 b1 b0 RRBOX RSHT FRBOX FSHT									
F6	xx	Log data check sum error xx: Data when judged erroneous (error sum)								
	01	Sensor slice level error of FDLS1.								
	02	Sensor slice level error of FDLS2.								
	03	Sensor slice level error of FDL 53								
	04	Sensor slice level error of FDLS4.								
	05	Sensor slice level error of FDLS5.								
	06	Sensor slice level error of FDLS6.								
	07 -8 08	Sensor slice lever error of DFSS.								
F8		Sensor slice level error of REJS.								
	09	Sensor slice level error of BPS.								
	0A	Sensor slice level error of BRS1.								
	0B	Sensor slice level error of BRS2.								
	0C	Sensor slice level error of BRS3.								
	0D	Sensor slice level error of EJSR.								
	0E	Sensor slice level error of EJSF.								
	0F	Sensor slice level error of BCS (op).								

							TITLE	
							F56-BDU ERROR CODE LIS	ST
							DRAW. NO. K3KD03234-0001	CUST
							N3ND03234 0001	
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRI	PTION	SIL	26/
DESIG	S		CHECK		APPR.		FUJITSU FRONTECH LTD.	/ 27

Semi- major	Additional Information	Detailed information	Detailed information		
major	81	Sensor-off check error of FDLS1.			
	82	Sensor-off check error of FDLS2.			
	83	Sensor-off check error of FDLS3.			
	84	Sensor-off check error of FDLS4.			
	85	Sensor-off check error of FDLS5.			
	86	Sensor-off check error of FDLS6.			
	87	Sensor-off check error of DFSS.			
	88	Sensor-off check error of REJS.			
	89	Sensor-off check error of BPS.			
	8A	Sensor-off check error of BRS1.			
	8B	Sensor-off check error of BRS2.			
	8C	Sensor-off check error of BRS3.			
	8D	Sensor-off check error of EJSR.			
	8E	Sensor-off check error of EJSF.			
	8F	Sensor-off check error of BCS (op).			
		Const. on once, on or or or or or			
F8	A1	Sensor-on check error of FDLS1.			
	A2	Sensor-on check error of FDLS2.			
	A3	Sensor-on check error of FDLS3.			
	A4	Sensor-on check error of EDISM			
	A5	Sensor-on check error of NDLS5.			
	A6	Sensor-on check error of FDLS6.			
	A7	Sensor-on checkeror of DFSS.			
	A8	Sensor-on check error of REJS.			
	A9	Sensor-on theck error of BPS.			
	AA	Sensor-on check error of BRS1.			
	AB	Sensor-on check error of BRS2.			
	AC	Sensor-on check error of BRS3.			
	AD	Sensor-on check error of EJSR.			
	AE	Sensor-on check error of EJSF.			
	AF	Sensor-on check error of BCS (op).			
	F0	Sensor level write DAC error.			
FC	00	Illegal operation due to non-notification of data.	F56S		
FD	00	Power off during count	F56S		

						F56-BDU ERROR CODE LIS	ST
L						DRAW. NO. K3KD03234-0001	CUST
EDIT	DATE	DESIG.	CHECK	APPR.	DESCRIPTION	S H E	27/
DESIG	3.		CHECK		APPR.	FUJITSU FRONTECH LTD.	/ 27